



空置 NC 说明: 这个实际上是板子内部 5v 正极给小型传感器供电  
输出使用不是电源!!!

许多客户都误把电源接到这引起了不必要的麻烦特此说明

NC Description: This is actually the board, the 5V positive to the  
small sensor power supply, output use is not power!!!

Many customers have mistakenly received the power supply, which  
has caused unnecessary trouble, I hereby say